





Thank you for purchasing our product. Before installing/operating the product, read the instructions carefully and retain them for future reference.

### 

- For installation, follow the steps described. Any damage caused by wrong installation shall be imputed to the users.
- To avoid a short circuit from occuring do not pull or modify the wires during installation.
- Do not disassemble or change any parts. Opening and dissassembling this unit will void any warranty.
- Maintenance and repairs should be executed by our professionals only.


#### **NOTE**


**AWARNING!** Certain procedures must be followed to avoid damages to yourself, to the vehicle or to others.

#### 1 ACCESSORIES



### 2 SPECIFICATIONS






• Effective temperature range	-10 ~ 60 °C
● Standard	JIS D 0203
<ul><li>Homologation</li></ul>	E-Mark / DOT Approved
●Size	Ø 181 X H 103.6 mm
●Weight	± 1185 g

●Effective voltage	DC 10 ~ 16 V
OFront position	DC 12V / 2.7W
○Low beam	DC 12V / 24.9W
○High beam	DC 12V / 20.2W

**NOTE** Design and specifications are subject to change without notice.

## 3 WIRING INSTALLATION INSTRUCTIONS



# 4 TROUBLE SHOOTING

The following situation do not indicate malfunction of the meter. Check the following before taking it in for repair.

Trouble	Check item
No LED indicator lighting up.	<ul> <li>◆Power supply cable may be disconnected.</li> <li>→Check if power supply cable is broken or disconnected.</li> <li>→Check if positive and negative poles are properly connected.</li> </ul>

 $\ensuremath{\mathbb{X}}$  If the problems still cannot be solved, contact our technical department for assistance.